典型特性曲线

Typical Characteristics Curves









可靠性试验

Reliability Test Items And Conditions

焊接指导（1）

Guideline for Solder

1. 使用烙铁人手焊接

Hand Soldering

2.

1. 贮存：

Storage