目录

电性参数

曲型特性曲线

可靠性实验

外形尺寸

包装

焊接指导

包装（1）

Packaging (1)

载带与圆盘尺寸



：

1. ㄚ β ㄐ (mm)Â
1. Size unit is mm (mm).
2. `E ±0.1mmÂ
2. The dimensional tolerance is ± 0.1mm.



使用注意事项（3）

Precautions (3)



When handling the product, touching the encapsulant with bare hands will not only contaminate its surface, but also affect on its optical characteristics. Excessive force to the encapsulant might result in catastrophic failure V