E

Part No. [redacted]



包装（1）

Packaging (1)

载带与圆盘尺寸 Belt and disk dimensions



：

1. (mm)

1. Size unit is mm (mm).

2. ±0.1mm

2. The dimensional tolerance is ± 0.1mm.

◇ [redacted] hole dimensions



焊接指导（1）

Guideline for Solder

1. 使用烙铁人手焊接

Hand Soldering

30W

300 3

LED

Manual welding is recommended only for repair and heavy industry situations. A soldering iron of less than 30W is recommended to be used in Hand Soldering. Please keep the temperature of the soldering iron under 300 while soldering. Each terminal of the LED is to go for less than 3 second and for one time only.

Be careful because the damage of the product is often started at the time of the hand soldering.

2.