












色区									
TA1	0.2743	0.282	0.2743	0.291	0.2862	0.2849	0.2818	0.2759	
TA2	0.2787	0.291	0.2831	0.3	0.2906	0.2937	0.2862	0.2849	
TA3	0.2831	0.3	0.2875	0.309	0.295	0.3029	0.2906	0.2939	
TA4	0.2875	0.309	0.2919	0.318	0.303	0.312	0.305	0.3029	
TA5	0.2919	0.318	0.3	0.327	0.3038	0.3209	0.3209	0.2994	
TA6	0.2963	0.3209	0.318	0.336	0.3082	0.3299	0.3082	0.3299	
TA01	0.2668	0.2881	0.2712	0.2971	0.2787	0.291	0.2787	0.291	
TA02	0.2712	0.2971	0.2756	0.3061	0.2831	0.291	0.2787	0.291	
TA03	0.2787	0.291	0.2831	0.3	0.2906	0.2937	0.2862	0.2849	









焊接指导（1）

Guideline for Solder

使用烙铁手工焊接







