










典型特性曲线

Typical Characteristics Curves



可靠性试验

Reliability Test Items And Conditions

--	--





外形尺寸

Outline Dimension

- Remarks:
- 1. mm
 - 2. $\pm$ $\pm 0.25\text{mm}$

包装 (1)

Packaging (1)



1. (mm)

1. Size unit is mm (mm).


2. $\pm 0.15\text{mm}$

2. The dimensional tolerance is $\pm 0.15\text{mm}$.




包装 (2)

Packaging (2)



◇ 标签说明 Label Expansion



焊接指导 (1)

Guideline for Solder

使用烙铁手工焊接

： 10mm 1mm 100









使用注意事项（3）

Precautions (3)

