











典型特性曲线

Typical Characteristics Curves



可靠性试验

Reliability Test Items And Conditions

--	--









焊接指导 (1)

Guideline for Solder

1. 使用烙铁手工焊接

Hand Soldering

2. 回流焊接



使用注意事项 (1)

Precautions (1)

1. 贮存:

Storage

